



Material Safety Data Sheet – TRANSPARENT GLYCERINE SOAP

Section I - Hazardous Ingredients				
Hazardous Components (Specific Chemical Identity, Common Name(s))	%	CAS Number	LD ₅₀ of Ingredient (specify species and route)	LC ₅₀ of Ingredient (specify species)
None				

Section II – Preparation Information		
Prepared by (Group, Department, etc.) Aquatech Skin Care Inc.	Telephone Number 416-532-2004	Preparation Date May 07, 2009

Section III – Product Information	
Product Identifier	WHMIS Classification (optional)
Product Use Personal Care	
Manufacturer's Name Aquatech Skin Care Inc.	Supplier's Name
Street Address 81 Kelfield Street, Unit 5	Street Address
City Toronto	Province Ontario
Postal Code M9W 5A3	Emergency Telephone 416-532-2004
	City
	Province
	Postal Code
	Emergency Phone

Section IV - Physical Data			
Physical State Solid	Odour and Appearance Clear transparent solid with characteristic odor	Odour Threshold (ppm)	
Specific Gravity NA	Vapour Density (air=1) NA	Vapour Pressure (mmHg) NA	Evaporation Rate NA
Boiling Point (°C) NA	Freezing Point (°C)	pH	Coefficient of Water/Oil Distribution

Section V - Fire or Explosion Hazard			
Flash Point (Method Used)	NA	Flammable Limits NA	LEL NA UEL NA
Extinguishing Media	NA		
Special Fire Fighting Procedures	NA		
Unusual Fire and Explosion Hazards	None		

Section VI - Reactivity Data

Stability	Unstable		Conditions to Avoid
	Stable	X	

Incompatibility (*Materials to Avoid*)

Hazardous Decomposition or Byproducts

Hazardous Polymerization	May Occur		Conditions to Avoid
	Will Not Occur	X	

Section VII – Toxicological Properties

Route(s) of Entry	Inhalation? No	Skin? No	Ingestion? No
-------------------	----------------	----------	---------------

Health Hazards (*Acute and Chronic*) No chronic effect known or expected.

Carcinogenicity	NTP? No	IARC Monographs? No	OSHA Regulated? No
-----------------	---------	---------------------	--------------------

Signs and Symptoms of Exposure Mild skin irritation, moderate eye irritation.

Medical Conditions Generally Aggravated by Exposure None Known

Section VIII – Preventive Measures

Respiratory Protection (*Specify Type*) NA

Ventilation	Local Exhaust	Special
	Mechanical (<i>General</i>)	Other

Protective Gloves Eye Protection

Other Protective Clothing or Equipment

Work/Hygienic Practices Wash thoroughly after handling.

Steps to Be Taken in Case Material Is Released or Spilled

Collect for proper disposal. Wash down spill area. Smooth surface will be slippery when wet.

Waste Disposal Method In accordance with all local, state, & federal regulation.

Precautions to Be Taken in Handling and Storing Do not freeze or store at temperatures exceeding 100F for good product stability.

Other Precautions None

Section IX – First Aid Measures

Inhalation

Ingestion Induce vomiting if large amounts are ingested.

Skin Contact Wash with water. Consult with physician if irritation persists.

Eye Contact Flush with water. Consult with physician if irritation persists.